

## Under Review Notification

**Raised By:** Steven Drouin  
**Date:** 19.03.27

**Product #:** D412-814  
**Product Name:** Replacement Crew Door Kit

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	PP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
D412-814-011/015/019	IIN-D412-814 Rev. C	Y	N	N	N	N	Y	Y	19-663	CHG# 001
D4465-041	D4465 Rev. C	Y	N	N	N	N	Y	Y	19-663	Drawing Update
D4467-041	D4467 Rev. D	Y	N	N	N	N	Y	Y	19-663	Drawing Update
D4468-041	D4468 Rev.C	Y	N	N	N	N	Y	Y	19-663	Drawing Update

### Description of Issue:

On drawing D4465-041 bolt need to be changed to from dash #11 to dash #56  
D4467-041 and D4468-041 Rivet change on drawings

D4465-065 need a deviation sign off for the bolt change by Engineering to ship  
REF CAR19-309

### Distribution:

VP Operations	Director of Engineering	Customer Support Manager	Technical Support
Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene